



# Invoice

**T.F. O'Brien & Co., Inc.**  
100 Denton Avenue  
New Hyde Park, NY 11040  
(516)488-1800 Fax: (516)488-3536

07/11/19  
Page 1

Ascension Lutheran Church  
145 Franklin Avenue  
Franklin Square, NY 11010

Ascension Lutheran Church  
145 Franklin Avenue  
Franklin Square, NY 11010

Call Slip Number	Invoice Date	Invoice Number
73785	07/11/2019	S63081

**Problem Reported:**

\*\*\* AC-AC Problem \*\*\*

Customer had tune up last month, if related no diagnostic, if not, \$77.50. Customer states one of the condensers fro Parish Hall is not coming on. Please call (516) 655-4635. FIRST CALL.  
COMM Expires: 05/31/2020

Tech Date  
JOHNG 07/11/2019

Brand	Model	Serial #
CARR	38HDC060521	18302X23069

The refrigerant used in your existing system is r-22 commonly referred to as "freon". This refrigerant is scheduled to be phased out as mandated by the federal government due to its ozone depleting characteristics. Currently no r-22 equipment is being manufactured because it is against the law and this refrigerant is to become obsolete. As these systems age and start to deteriorate and require costly repairs we strongly recommend that you consider replacement before the phase out period ends. In addition, should your system require refrigerant as it ages and seals weaken, this refrigerant may not be available.

Found condenser motor running hot, high amperage 1.55amps. Refer to office to check for condenser blower motor, capacitor and time delay board price and availability.  
Carrier condenser.  
Model:38hdc060521  
Serial:1802X23069

Motor 655.44  
187.93  
340.00  

---

1183.37

Also recommended condenser coil cleaning. Triple coil and very dirty cutting off efficiency, very hot air from condenser# is blowing into condenser #2 creating an increase in amperage consumption. Quoted \$544.69+ tax each.